

Message

---

**From:** Ryan, Jeff [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=C6088FC0757D4BBF825E9B39311E35BE-RYAN, JEFF]  
**Sent:** 3/14/2019 4:42:54 PM  
**To:** DiMartino, John [DiMartino.John@epa.gov]  
**Subject:** FW: Surveillance Checklist-Saint-Gobain PTFE Sintering Facility-Hoosick Falls, New York  
**Attachments:** Hoosick Falls PTFE surveillance checklist 190314.docx; SUMMA Canister Sampling for PFAS.docx; 0031868-QP-1-0 AEMD PFAS QAPP-NYSDEC Test Plan-FINAL\_signatures.pdf; Midget Impinger Sampling for PFAS.docx; D-EMMD-AQB-SOP-3067-1\_Aerodyne-Tofwerk\_CIMS\_Riedel.pdf

Here's the audit package, the qapp and SOPs.

---

**From:** Wright, Bob  
**Sent:** Thursday, March 14, 2019 12:00 PM  
**To:** Ryan, Jeff <Ryan.Jeff@epa.gov>; Krebs, Ken <krebs.ken@epa.gov>  
**Cc:** Nessley, Libby <Nessley.Libby@epa.gov>  
**Subject:** Surveillance Checklist-Saint-Gobain PTFE Sintering Facility-Hoosick Falls, New York

I have prepared the attached checklist for the surveillance to be conducted in Hoosick Falls. Please pass it on to the Region 2 auditor to allow sufficient time for review before the testing starts. If they are not already in the auditor's possession, also please send the associated QAPP and SOPs. Please note that the surveillance is limited to the PFAS emissions sampling by National Risk Management Research Laboratory (NRMRL) staff using SUMMA canisters and midget impinger trains. Thanks.

Respectfully,  
Robert S. Wright  
Air and Energy Management Division  
US Environmental Protection Agency  
Mail Code E343-03, Room E330C  
109 TW Alexander Drive  
Research Triangle Park, NC 27711  
Phone: 919-541-4502  
FAX: 919-541-1536  
E-mail: [wright.bob@epa.gov](mailto:wright.bob@epa.gov)